

# Results of Magnetic Measurements in LEReC Solenoid #1 (Sl. No. 16046)

*Animesh Jain*

*September 17, 2015*

**BROOKHAVEN**  
NATIONAL LABORATORY

*a passion for discovery*



U.S. DEPARTMENT OF  
**ENERGY**

Office of  
Science


# LEReC Solenoid Details

- 3 Solenoid coils – One *Main coil* and two *Bucking Coils*:
  - The Bucking Coils are expected to reduce the fringe field from the main solenoid to less than 1 Gauss at a distance of ~210 mm from the axial center.
  - Nominal operating current is < 15 A for all solenoid coils.
  - Goal is to get  $\int [B_z(z)]^2 dz \geq 4 \times 10^{-5} \text{ T}^2 \cdot \text{m}$
- Horizontal and vertical dipole correctors:
  - Operating current = 0.8 A (max.)
  - Expected dipole field integral  $\sim 10^{-5} \text{ T}\cdot\text{m}$  at 0.8 A.
  - Needed to correct transverse fields from any misalignment of the solenoid axis.
- 158.5 mm dia. clear aperture; 200.2 mm total length.


# LEReC Solenoid Measurements

- Hall probe scans at a fixed current in the main and bucking solenoid coils:
  - Measured only axial component,  $B_z$ , with a single probe.
  - Currents of main and the bucking coils were determined to obtain the same fields at the axial center as in Wuzheng Meng's simulations.
    - Main current = 14.0 A, Bucking coil current = 14.8 A
  - Z-values from -400 mm to +400 mm in 2 mm steps
  - On-axis ( $r = 0$ ) and every 45 deg. off-axis at  $r = 10$  mm.
- Hall probe loop 0 A to 15 A at axial center, main solenoid only.
- Rotating coil measurements (integral coil, 0.914 m long):
  - Horizontal and vertical field correctors: full bipolar loops
  - Main & bucking solenoids separately, and all in series: loop from 0A to 15A.

# LEReC Solenoid: Hall Probe Setup




# Solenoid Field Profile On-Axis (Main + Buck)




# LEReC Solenoid: Computed Field Profiles

## Axial Field Profiles from Wuzheng Meng




# Solenoid Fringe Field On-Axis (Main + Buck)

LEReC Solenoid #01(16046); 25-Aug-15; Main=13.97A, Buck = 14.80 A




# Solenoid Field Integral Off-Axis (Main + Buck)

LEReC Solenoid #01(16046); 25-Aug-15; Main=13.97A, Buck = 14.80 A




# Solenoid Field at Z = 0, Off-Axis (Main + Buck)




# Integral of $[B(z)]^2$ Off-Axis (Main + Buck)

LEReC Solenoid #01(16046); 25-Aug-15; Main=13.97A, Buck = 14.80 A




# DC Loop in Main Coil at $(r,z) = (0,0)$

LEReC Solenoid #1; 26-Aug-15; Main Coil Loop with Buck at 14.8 A



# DC Loop in Main Coil at $(r,z) = (0,0)$

LEReC Solenoid #1; 26-Aug-15; Main Coil Loop with Buck at 14.8 A





Cycle 1 measured after 5 prior cycles to 140 A.

# Rotating Coil Measurements

- Measuring coil is 0.914 m long, but the magnet is only 0.2 m
  - Good for capturing all the fringe field
  - But sees a lot of extra transverse field from earth's field.
  - Need to subtract background fields to get true contribution from the magnet
- Measurements were carried out in two ways:
  - Several measurements at two different currents (0 A and 15 A for solenoids and +0.8A and -0.8 A for the correctors). True fields obtained by the slope of a straight line fit to two currents.
  - Full excitation curves measured from  $I_{min}$  to  $I_{max}$  (0 A to +15 A for solenoids and -0.8 A to +0.8 A for the correctors). True fields obtained by the slope of a straight line fit to both the up ramp and down ramp data.
    - This also gives non-linearity such as hysteresis.
  - Results from both methods are nearly identical.
  - Only the full excitation curve results are presented here.

# Solenoid Transverse Field Integrals

- LEREC-SOL\_16046\_0005\_001.202 MAIN ONLY
- ×— LEREC-SOL\_16046\_0006\_001.202 BUCKS ONLY
- ▲— LEREC-SOL\_16046\_0007\_001.202 MAIN + BUCKS IN SERIES



$$\int [B_y(z)] dz = 9.035 \times 10^{-7} \text{ T} \cdot \text{m/A (Main)}$$

$$= -1.208 \times 10^{-6} \text{ T} \cdot \text{m/A (Bucks)}$$

$$= -3.230 \times 10^{-7} \text{ T} \cdot \text{m/A (Main + Bucks)}$$



$$\int [B_x(z)] dz = 1.411 \times 10^{-6} \text{ T} \cdot \text{m/A (Main)}$$

$$= -1.151 \times 10^{-6} \text{ T} \cdot \text{m/A (Bucks)}$$

$$= 4.111 \times 10^{-7} \text{ T} \cdot \text{m/A (Main + Bucks)}$$

# Corrector Field Integrals

■ LEREC-SOL\_16046\_0009\_001.202 (HORIZONTAL FIELD DIPOLE)  
× LEREC-SOL\_16046\_0010\_001.202 (VERTICAL FIELD DIPOLE)



$$\int [B_y(z)] dz = -1.061 \times 10^{-5} \text{ T} \cdot \text{m/A}$$

$\sim 8.49 \times 10^{-6} \text{ T} \cdot \text{m at } 0.8 \text{ A}$

$$\int [B_x(z)] dz = 1.058 \times 10^{-5} \text{ T} \cdot \text{m/A}$$

$\sim 8.46 \times 10^{-6} \text{ T} \cdot \text{m at } 0.8 \text{ A}$

# Expected Transverse Field Integrals

- With main solenoid coil at 13.97 A and the bucking solenoid coils at 14.8 A, the expected transverse field integrals are:

$$\int [B_y(z)] dz = -5.257 \times 10^{-6} \text{ T} \cdot \text{m} \quad \int [B_x(z)] dz = 2.677 \times 10^{-6} \text{ T} \cdot \text{m}$$

(neglecting any background fields)

- The axial field integral is  $\int [B_z(z)] dz = 2.743 \times 10^{-3} \text{ T} \cdot \text{m}$
- This implies a misalignment of  $\sim 2$  mr in pitch and  $\sim 1$  mr in yaw. This could either be from misalignment of solenoid magnetic axis to the mechanical axis, or a misalignment of the measuring coil, or both.

# Summary

- Hall probe scans were carried out to measure only the  $B_z$  component of the field – both on-axis, and at  $r = 10$  mm.
- The magnet meets the focusing strength requirement.
- The fringe field drops to less than 1 Gauss well before the expected 210 mm from the center.
- There is a hysteresis of  $\sim 3.5$  Gauss in the field from the main solenoid coil at the center of the magnet (with  $I_{buck} = 14.8$  A)
- The corrector strengths are approx. 85% of the expected strengths, but are sufficient to compensate for the level of transverse fields seen in magnet #1 (serial #16046).
- The measured misalignment of magnetic and mechanical axes is  $\sim 2$  mr in pitch and  $\sim 1$  mr in yaw, but could be measurement error because of uncertainty in rotating coil placement.