

BROOKHAVEN NATIONAL LABORATORY

MEMORANDUM

Date: 11/17/89
To: E. Lessard
From: J. Alessi *g.a.*
Subject: Review of the Linac security system

Following your memo dated April 20, 1989, the ad hoc committee of P. Montemurro, B. Briscoe, D. Pope, and myself (Chairman) met eight times to review the logic of the design of the security system for High Hazard Radiation Areas in the Linac, HEBT, BLIP, and REF/NBTF. We also compared the design to existing hardware. REF/NBTF was reviewed only at the point where it ties in to the Linac security system, and the Linac system only serves as a reachback in case of a failure of the REF primary or redundant system. Their system is otherwise independent, and had been recently reviewed since it is a new installation. *removed*

Throughout the review, the committee was assisted by A. McGeary, who provided us with all wiring diagrams for the security system (a list is given in Appendix 1), a logic diagram which he had generated from the wiring diagrams (included as Appendix 2), and a preliminary test procedure for the security system. We also received a description of the BLIP security system elements from L. Mausner. The committee started by generating a plan drawing of the Linac/HEBT/BLIP area, which showed the location of all elements in the security system. This drawing is attached as Appendix 3. Working from this drawing, we identified for each gate, crash button, sensor, etc., the appropriate action which should be taken in the security system, assuming the linac is operating. For any one of the actions taken to inhibit beam, there is in addition one level of reachback, which invokes another method of shutting off the beam if the requested action does not occur. These reachbacks were also included in our list. This list was generated independent of what actually existed in the security system wiring. We then went through both the logic and wiring diagrams and checked that the actions actually taken agreed with our list. This was in fact the case, with the exception of one element which should have been included as a reachback action (see #1 in the Findings section). In many cases there were additional actions taken in the hardware which were not essential, but gave additional safety. These were added to our list, so that the final list, included as Appendix 4, shows what actually exists at present. The elements in the system which are part of the High Hazard Radiation security are marked by

asterisks in Appendix 4. The function of each of these elements is shown in Appendix 5. Each of these was checked for redundancy by going and looking at the actual devices and verifying the redundant switches. We then went through the wiring diagrams to verify the redundancy from input to output, and found one point within the relay logic where the redundancy is lost. This is discussed in #2 in "Findings". Finally, all elements that were part of the High Hazard security, as well as all reachbacks, were followed through the wiring diagrams from input to all the resultant actions, and all relays in the string were noted. The test procedure was then reviewed to make sure that the complete string was being tested in every case. A couple of additions or corrections were noted and A. McGeary has made the necessary revisions to the test procedure.

It should be noted that the ability to do "coinjection" (i.e. high intensity H⁻ to BLIP/REF and low intensity polarized H⁻ to the AGS) is no longer in the security system. A new system to allow coinjection is being developed by P. Yamin.

HIGH LOW
VALUE +
BIS XMR

Findings

1. The polarized bending magnet (action 6 in Appendix 4) is not included in the reachback circuits for Beam Stop 2 failure (E.7. and E.8.) or LBM1 failure (E.13.).

2. There is a portion of the relay logic for the gates and crash buttons which is not redundant. All inputs are redundant, and two independent actions occur in each case to inhibit the beam. However, the primary and redundant system relays are placed in series to activate relays A21HK7 and A21HK8 on drawing D09-E1776. A single-point failure could occur if a voltage were inadvertently applied at this location.

3. We found no discrepancies between the logic diagram and the wiring diagrams. The logic diagram does not fully show the redundancy of the system, but including the redundancy would complicate the diagram to the point that it would be difficult to follow the functionality. Other than the items above, the system seems to perform as it should. There are a couple of minor changes which could be made in the logic, unrelated to High Hazard Safety but rather regarding some conditions to allow equipment testing when the Linac is off. The committee will present these to A. McGeary for future consideration.

Recommendations

1. We recommend that the polarized bending magnet be added to the reachbacks for Beam Stop 2 and LBM1. This should be corrected before polarized H⁻ is run again (not scheduled for FY90).


FAILURE IS TO TIME RFP

2. We recommend that the non-redundant portion of the relay logic, described in Finding 2, be changed so that the primary and redundant systems are kept separate throughout the relay logic. However, since this is an extremely unlikely failure mode (the point is inside a locked security cabinet), we recommend that the change not be made before the AGS is turned back on, but rather that it be made at a future time (a maintenance day, for example). This change is occurring at a critical location in the security logic, and its implementation should not be rushed, but rather the proper solution should be addressed carefully, and then fully tested.



cc:

- D. Beavis
- B. Briscoe
- D. Lowenstein
- A. McGeary
- P. Montemurro
- D. Pope


Record#	OLDNO	ORCADNO	REVISION	DATE	SIZE	AREA	NAME
191	D09-E1770-5	LINAC70	A	08/16/89	C	LIN	LINAC SS PANEL LAYOUT
192	D09-E1771-3	LINAC71	A	08/16/89	C	LIN	LINAC SS TANK 1 GATE
193	D09-E1772-3	LINAC72	A	08/16/89	C	LIN	LINAC SS PLUG DOOR
194	D09-E1773-3	LINAC73	A	08/16/89	C	LIN	LINAC SS HEFT GATE
195	D09-E1774-3	LINAC74	A	08/16/89	C	LIN	LINAC SS INTERNAL GATES
196	D09-E1775-3	LINAC75	A	08/16/89	C	LIN	LINAC SS CRASH BUTTONS
197	D09-E1776-3	LINAC76	A	08/16/89	C	LIN	LINAC SS PRIME INTLK
198	D09-E1777-3	LINAC77	A	08/16/89	C	LIN	LINAC SS BEAM STOPS
199	D09-E1778-3	LINAC78	A	08/16/89	C	LIN	LINAC SS REDUNDANT SW'S
200	D09-E1779-3	LINAC79	A	08/16/89	C	LIN	LINAC SS REDUNDANT CRASH
201	D09-E1780-3	LINAC80	A	08/16/89	C	LIN	LINAC SS LIGHT PANEL
202	D09-E1781-3	LINAC81	A	08/16/89	C	LIN	LINAC SS EXTERNAL FACILITIES
203	D09-E1782-3	LINAC82	A	08/16/89	C	LIN	LINAC SS MCR INTERFACE
204	D09-E1783-3	LINAC83	A	08/16/89	C	LIN	LINAC SS COCKCROFT WALTON
205	D09-E1784-4	LINAC84	A	08/16/89	D	LIN	LINAC SS PRIME CKT CABLING
206	D09-E1785-3	LINAC85	A	08/16/89	C	LIN	LINAC TANK RF SS
211	D09-E1855-4	LININTLK	A	08/17/89	D	LIN	LINAC BENDING MAGNET 1&2 INTLK CHASSIS
214	D09-E1887-2	LIN60DEG	A	08/17/89	B	LIN	LEBT 60 DEG BENDER AND SEB ENERGY BYPASS
216	D28-LE1357-3	LINTCTRL	A	08/17/89	C	LIN	AGS/LINAC CONTROLS SCHEMATIC
224	D28-LE1357	LICORAMO	A	08/17/89	A	LIN	LINAC COINJECTION & RADIATION MONITORS
233		LEBT24	A	08/22/89	D	LIN	LOW ENERGY BEAM TRANSPORT 24V POWER SUPPLY
238		BNAG4&5		/ /	A	LIN	LINAC BEAM ONLY BENDING MAGNET 4&5 SS INTLK
275		LINLOGIC	G	07/20/89	C	LIN	LINAC SECURITY SYSTEM LOGIC DIAGRAM
		HEFTGATE		8/24/87	E		HEFT GATE - AGS DOOR



(Note 1) (SEL. SW.)
LOW INTENSITY MODE
(Note 2) (SEL. SW.)



- NOTES
1. Method to insure low intensity operation to be determined and required to be in place before this signal is enabled
 2. Jumper if single P.S. used for LEFT BM 1/2
 3. Use to run RFQ2 into Lines. Disable Low Intensity mode.




BROOKHAVEN NATIONAL LABORATORY			
UTRON, N.Y. 11972			
Title: APPROVED LINAC SECURITY LOGIC			
Doc#	Document Number	A.J. McGeary	REV
0	LINLOG		0
Date:	July 20, 1982	Sheet	of 1

8

7


B

A



6

5



KIRK KEY BOX
TANK NO. 1
HV POWER SUPPLY

MOD 9 QUAD
PULSERS

TANK 2

TANK 8

TANK 9

TANK 9
GATE

TANK 1
GATE

6


5



4

3

B



A


4

3

2

1

ITEM NO.	QTY.	DESCRIPTION	MAT'L, DWG. NO. OR BNL NO.
----------	------	-------------	----------------------------



BROOKHAVEN NATIONAL LABORATORY
 ASSOCIATED UNIVERSITIES, INC.
 UPTON, N.Y. 11973

LINAC SECURITY SYSTEM

DRAWN BY J.SCOTT FILE NAME: LSS.DWG 7/21/89

2

1 *AUTOCAD

APPENDIX 4

LINAC SECURITY SYSTEM

ACTION

A. Gates, Plug Doors

*1. Tank 1 gate	1,2,3,6,8	2 switches (one magnetic)
2. Tank 9 gate	1,2,3,6,8	1 switch
*3. HEBT plug door	1,2,3,6	2 switches
4. HEBT sliding gate	1,2,3,6	1 switch
5. BLIP tunnel gate (HP)	1,2,3,6	1 switch
*6. BLIP inspection plug	9,10	2 switches
7. HEBT gate (HP)	1,2,3,6	1 switch
8. Heavy ion security gate	locked for HI running	No switches
*9. AGS-HEBT gate	1,2,3,6	2 switches

B. Crash Buttons

*1. Tanks	1,2,3,6,8	} 2 contacts, 1 norm. open, 1 norm. closed Primary - 110 V relay drops out Redundant - 12 V relay energizes
*2. HEBT	1,2,3,6	
*3. BLIP	1,2,3,6	
4. AGS (NCR crash of Linac beam)	1,2,3,6 (not redundant; equipment protection)	

C. Radiation Monitors

1. BLIP high radiation - panel	} (3 connected in series)	9,10	EBERLINE Model RMS II
2. BLIP high radiation - hot cell			
3. BLIP high radiation - pump pit			
4. Booster-Linac chipmunks (2)		2 (not high rad. hazard)	

D. Sensors

1. BLIP vacuum failure	9,10	Ashcroft pressure switch
*2. BLIP low shaft water level	9,10	2 conductivity probes (HEKONTROL HEK 54)
3. shaft water leak	9,10	2 sensors (Cond. probe HEK 54)

E. Reachbacks

1. REF D3 not off (command off)	9,10	Aux. contact on relay for primary power	<i>Rem Nov</i>
2. REF D4 not off (command off)	9,10	Aux. contact on relay for primary power	
3. HEBT BM1 not off (command off)	1,2,3,6	Aux. contact on relay for primary power	
4. HEBT BM2 not off (command off)	1,2,3,6	Aux. contact on relay for primary power	
5. BS-1 cooling water failure	4	Shur-flo	
6. BS-1 not closed (command closed)	4	1 switch	
7. BS-2 cooling water failure	4,5	Shur-flo	
8. BS-2 not closed (command closed)	4,5	1 switch	
9. NZ-304 cooling water failure	1,2,3,6	Shur-flo	
10. NZ-304 not closed (command closed)	1,2,3,6	2 switches in series	
11. NZ-307 cooling water failure	1,2,3,6	Shur-flo	
12. NZ-307 not closed (command closed)	1,2,3,6	2 switches in series	
13. LBM1 not off (command off)	5	Aux. contact on relay for primary power	

" AGS B.S. Failure "

Above actions are when linac is operating. Alternative of 2,7 for linac testing

F. Actions used to inhibit beam

1. BS-1 closed	Interrupt primary power	<i>Rem Nov</i>
2. BS-2 closed	Interrupt primary to 30 kV ps	
3. LBM1 (and L2BM1) ps off	Interrupt primary to motor generator	
4. RFQ2 HV ps off	Interrupt primary power	
5. Pit 2 H.V. off	Kirk key on primary pwr to 60 kV ps	
6. Pol. EM off	Interrupt rf driver card (not part of high hazard)	
7. Tank 1 rf off	Interrupt primary power	
8. All tank rf off	Interrupt primary power	
9. HEBT BM1 off	Interrupt primary power	
10. HEBT BM2 off	Interrupt primary power	

APPENDIX 5

Elements in the high hazard radiation security system:

- I. Elements to keep personnel out of the Linac/HEBT tunnel:
 1. Tank 1 gate (2 switches)
 2. HEBT plug door (2 switches)
 3. AGS-HEBT gate (2 switches)
 4. Crash buttons (except "AGS Crash") - primary and redundant system
- II. Elements to ensure proper shielding at the BLIP target:
 - BLIP inspection plug (2 switches)
 - BLIP shaft water level (2 sensors)
- III. Elements to keep beam out of AGS (AGS review, linac only enters as reachback)
 - Beam stops NZ304 and NZ 307
- IV. Elements to keep beam out of BLIP
 - HEBT dipoles BM1 and BM2
- V. Elements to keep beam out of REF (REF review, linac only enters as a reachback)
 - REF dipoles D3 and D4
- VI. Elements to keep beam out of the linac
 - RFQ line : BS-2 and BS-1
 - Pit 2 : BS-2 and LBM1
 - Polarized H- : BS-2 and LBM1
 - Alternative for all 3 lines is BS-2 closed and tank 1 rf locked off

Note:

There is one level of automatic reachback in the event of a failure of any of the devices used to keep beam out of an area.
(except polarized H-; see "Findings")

Elements in the security system which are not part of the high hazard, redundant system:

- Tank 9 gate
- HEBT sliding gate
- BLIP tunnel gate
- HEBT gate
- Heavy ion security gate
- Blip radiation monitors (panel, hot cell, pump pit)
- Booster-Linac chipmunks
- BLIP vacuum failure
- BLIP shaft water leak
- Tank rf (except Tank 1)