

SPIN2 HYSTERISIS RAMP SLOW FACTORS

And Other Helpful Notes – 11/30/01

Starting From Zero Current

Here To Park is Slow Factor 3

Here To Injection is Slow Factor 9

Here To Last is Slow Factor 3

Here To Injection is Slow Factor 6

Here To Park is Slow Factor 9

Here To Injection is Slow Factor 9

Here To Last is Slow Factor 2

Here To Injection is Slow Factor 6

Here To Park is Slow Factor 9

Here To Injection is Slow Factor 9

Before running the **Blue** or **Yellow** quench recovery programs, manually ramp the current in all of the power supplies to zero current.

When Running the **Blue Link** Quench Recovery Program, FIRST Disable the **Yellow Link** Quench Recovery Program

When Running the **Yellow Link** Quench Recovery Program, FIRST Disable the **Blue Link** Quench Recovery Program