


INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM --APRIL 2015

- LINAC_Rf
Mod8 8618 tube change
- PS_Booster
1CD module PLC replaced
- PS_EXP
STAR Power Supply Problems
- PS_RHIC
Replaced yo9-snk7-2.3 supply
- Rf_RHIC
Air cooling for 9MHz, 28MHz
tuners, and storage cavity damper
control
- E-lens
Power supply problems 3X
- BLM_PullsPermit
5X
- Experiments
PHENIX detector problems



Run15 availability

