





RHIC Status



RHIC Status


File Acquire Orbit Correction



Blue Sector 10 D19

BO10-D15~20

BO11-D15~20



Status

Voltage Tap:

1. 3/16: still looked good, recovered from quench
2. 3/17: the first time this tap has a problem, but don't know.
3. 3/18: beam induced quench, did not look as bad as 3/17, but we never recovered
4. Good or bad? How about others? -> How to protect.