Official WEB Counters RHIC Physics Fy05

Main QLI Faults	*Qty*
Beam Induced Quench	37
Quench Detector Faults	20
IR Supply Faults	51
QPA Faults	6
Main PS (Total) Faults	6
Controls 6B Yellow Permit Fail	0
Controls Related	13
Operations Error	12
Cryo Related	4
Power Failure	7
Other	29
Power Supply Induced Quench	0
Maintenance Related	20
Totals for the Main QLI's:	**185**

Snake / Spin Quench Faults	*Qty*
Beam Induced	2
Quench Detector Faults	0
Power Supply Faults	0
QPA Faults	0
Operations Error	1
Cryo Related	3
Power Failure	2
Other	5
Maintenance Related	0
Totals for the Snk / Spn QLI's:	**13**

Data Researched and Compiled by Gregory P. Hanover 6/30/2005 3:25 PM