Accelerator Support and Maintenance

Run 15: p-Au

Schedule for May 13th

Time	Activity	Group
After last fill	Turn down OPPIS source Apply CA LOTO to AGS and Booster	MCR CAS
0600	Siemens Spin down test	APSG
0730	Prepare to Dump	MCR
0745	Dump beam ramp down, Open Experimental areas	MCR
0800	Tunnel access begins: XA sectors 6, 10 & 12. RA: Sectors 2, 4, 8 CA: Uup, U, down, W,X, Y	MSG
1200	Sweeps in areas where work has completed begins. Remove LOTO Restore Booster to Operation	CAS/MCR
1400	Remove AGS LOTO, restore to Operation OPPIS Source work complete	CAS/MCR
1500	Sweep all but 2z1, STAR, PHENIX	CAS/MCR
1530	Perform Hysteresis ramp after 2z1 secured, sweep experiments	CAS/MCR
1600	RHIC secured, begin restoration of Physics	MCR/AP

Scheduling Planning Meeting

- Here today at 2:30pm