




Procedure to monitor the RHIC Tunnel Lead-Tree temperature with LogView program.

- 1 Telnet or Log onto any acnsun station.
- 2 Type <StartUp>. Note: Do not type the "<>", only letters inside the <>.
- 3 From the StartUp windows, select:
 - A Start
 - B General programs ...
 - C LogView
 - a RHIC
 - b Cryo
 - c IceBallMan
 - (1) Click the "Show Logging Request Files" option on the center sub-window, then pick the temp-sensor string "Tempxxx.logreq" you are interested in.
 - (2) From the upper right sub-window "Data to Display", select sensor(s) that you want to display.
 - (3) The final step is to pick the date, which located in lower right sub-window labeled "Fill Start Stop", and click the Display Data button that below the date sub-window.



4 Examples of Temp sensor graphs are as follows:



5 To understand and to analyze the LogView graphs, please refer to RHIC Tunnel Temperature Sensor Data Analysis Documents.