



Memo

date: September 30, 2009

to: RSC

from: D. Beavis 

subject: Modification of the Fence at 2 O'clock

There is a section of double fence at 2 O'clock. The first fence is at the top of the retaining wall and was part of the original construction of the area. The second fence has a section that runs parallel to retaining wall fence about 4 feet onto the berm and was placed to keep people off the berm and the IR roof. The inner fence needs to be taken down to remove trees for stochastic cooling. The request has been made to leave the fence down and use the outer fence on the retaining wall as the entrance barrier.

D. Phillips and I inspected the inside of the berm area on Sept. 28, 2009. On Sept. 30, 2009 I inspected the fence on the outside from the top of building 2000A. The fence has a low spot at the south end of the building that is 4 feet 8 inches high. In addition the external fence supports are on the outside of the fence which makes it easier for someone to scale the fence from the top of building 2000A.

The outside fence is a reasonable barrier to prevent access.

I have signed an ECN and a work plan for the removal of the permanent removal of the inner fence. The RCD representative should decide if specific posting should be placed on the fence. It should be kept in mind that the access ladders for the roof are locked during operations, but at some point the decision may be made to unlock some roof ladders.

CC:

- C. Folz
- A. Pendzick
- D. Phillips
- A. Drees