

BLIP Operations – 118 days of operation

- **Safety** – target box failure after beam dump tuning.
 - Resulted in ability to load thorium target at 180 MeV rescheduled.
- **Production**
 - Both Arronax and BNL target being processed this week.
- **Target box repaired (after hot-box entry)**
- **116 MeV beam on.**
 - Replace RbCl targets from previous week.

Target box failure

Water supply

Degrader that was launched out of box


Water bracket - obstruction

Lid of Box 1


Beam

Box 2

Box 1



Current delivered to BLIP 18 Dec – Apr – 15



Total Integrated Current at BLIP vs Days of Operation

