



Time Meeting
Apr 29, 2014

Agenda

- Safety
- Schedule
- Machine and system reports



Safety and training

- Ed Lessard



Schedule

1. Monday, e-lens and beta squeeze study at the end of store, 12:00-1:10pm.
56 cavity conditioning, 1:10-5:10pm.
2. Wednesday, maintenance day, AGS access starts 6:00am, dump beam at 7:00am, sweep at 12:00pm sector 4 for 56 conditioning, 18:00pm back to physics
3. Thursday, ~4hrs reserved for 56 cavity test, plus ~20 mins for unequal frequencies study at injection.



Machine and system reports

- [RHIC](#)
- [STAR](#)
- [PHENIX](#)
- AGS
- [BLIP](#)
- APEX
- Maintenance
- [Operations](#)
- [56 MHz](#)
- RCF

Guillaume Robert-Demolaize

Qiu Hao

Klaus Dehmelt

Haixin Huang

Phil Pile

Yun Luo

Paul Sampson

Peter Ingrassia

[Qiong Wu](#)

Michael Ernst



Next Time Meeting

- Next Time Meeting: Tuesday, May. 6
1:30PM, Snyder