

Linac Status

D. Raparia

March 17, 2015

Time Meeting

Status

- On Friday changed 7835 for mod 5
- Power outage on Saturday
- Linac was back and running with both polarized and high intensity beams since Sunday 4 PM

2 Blower motors in Fil. PS for 7835

4 Blower motors in Cap banks/modulator

4 Switches mod

2 Circuit Breakers

Transformer in mod 8 modulator

Regenerate all cryo-pumps

High intensity source recovery

OPPIS recovery

Fuses

Status (cont..)

- Maintenance on Monday
 - Tube 8618 in mod 3
 - Chip for LPT32 in mod 4
 - Doors for modulators in mod 1,2,3,5,6
 - Replace fan in solenoid PS 1
 - Swap sol. PS1 and 2
 - Conditioned tank 6-9 at 6.67 Hz for 200 MeV run for BLIP on Mar 20th

Blower Motors



Switch



Circuit Breaker



Transformer



Daily Average Current for BLIP



