

INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM -- MAY 2015

LINAC Rf

Mod 3 problems

BLM Pulling Permit

2X

Experiment

STAR pixel detector


Quench Detect

Cfe-9b-qd1 – radiation upset

Power Supply RHIC

yi7sxd2 quench indication

yi6-q89ps



Run15 availability

